



Quin Systems Limited
Programmable Transmission System
MiniPTS 1+1 Installation Manual

Issue 9
October 1998
(MAN535)

Important Notice

Quin Systems reserves the right to make changes in the products described in this document in order to improve design or performance and for further product development. Examples given are for illustration only, and no responsibility is assumed for their suitability in particular applications. Reproduction of any part hereof without the prior written consent of Quin Systems is prohibited.

Although every attempt has been made to ensure the accuracy of the information in this document, Quin Systems assumes no liability for inadvertent errors.

Suggestions for improvements in either the products or the documentation are welcome.

Relevant Directives

The product is designed to be incorporated into a system for the control of machinery, and needs external equipment to enable it to fulfil this function. It must not be relied upon to provide safety-critical features such as guarding or emergency stop functions. It must not be put into service until the machinery into which it has been incorporated has been declared in conformity with the Machinery Directive 89/392/EEC and/or its relevant amendments.

The installation instructions in this manual should be followed in constructing a system which meets requirements.

The product as normally supplied has low voltages accessible to touch, and must be mounted within a suitable cabinet to meet any required IP rating to BS EN 60529.

Contents

1.	Introduction	5
2.	Unpacking and Inspection	6
3.	System Specifications	7
3.1	Mechanical specification	7
3.2	Environmental specification	7
3.3	Power supply specification	7
3.4	Relevant directives	8
4.	Mounting Details	9
5.	Connections	10
6.	Electrical Installation	14
6.1	General	14
6.2	Power supply	15
6.3	Earth connections	16
6.4	Connecting the motor to the drive	17
6.5	Encoder signals	18
6.6	Command signal and drive enable	20
6.7	Digital inputs and outputs	22
7.	Safety - Using Guards and Limits	23
8.	Encoders	24
8.1	What is an encoder ?	24
8.2	Types of encoders	24
8.3	Choosing an encoder	28
8.4	Encoder installation	29
9.	Motors	30
9.1	Types of motor	30
9.2	Choosing a motor	33
9.3	Mounting the motor	35
9.4	Connecting the motor to the load	35
10.	Tuning the Position Control Loop	36
10.1	General	36
10.2	Control algorithm	36
10.3	Monitoring the performance	37
10.4	A simple tuning procedure	37
11.	Testing the System	42
11.1	General	42
11.2	Serial port	42
11.3	Encoder	43
11.4	Motor enable relay	43
11.5	Command signal	44
11.6	Digital signals	45

12.	Electrical Details	46
12.1	Signal names	46
12.2	Encoder input circuits	46
12.3	Isolated input and output circuits	47
12.4	Electrical characteristics	48
13.	Board Configuration	49

Figures and Tables

Figure 1.	Fixing centres for the MiniPTS 1+1.	9
Figure 2.	MiniPTS 1+1 front panel layout	10
Table 1.	Serial port A connections	11
Table 2.	Serial port B connections	11
Table 3.	SERVOnet (CANbus) connections	11
Table 4.	Encoder connections : S4, S5	12
Table 5.	Input/output connections : T1 and T2	12
Table 6.	Power supply connections : T3	13
Table 7.	Analogue signal connections : T4	13
Figure 3.	General installation arrangement.	14
Figure 4.	Mains supply installation.	15
Figure 5.	Earth connections.	16
Figure 6.	Motor connections.	17
Figure 7.	Encoder connection.	18
Figure 8.	Typical encoder connections.	19
Figure 9.	Command signal connection.	20
Figure 10.	Typical analogue output connections.	21
Figure 11.	Input and output circuits	22
Figure 12.	Single phase encoder signal.	24
Figure 13.	Incremental encoder signals and multiplication.	25
Figure 14.	Incremental encoder marker signals.	26
Figure 15.	Torque-speed curve for a d.c. motor.	30
Figure 16.	Torque-speed curve for an a.c. motor.	31
Figure 17.	Torque-speed curve for a brushless motor.	32
Figure 18.	Motor performance for detuned system.	38
Figure 19.	Motor performance for faster moves.	39
Figure 20.	Motor performance with oscillation.	40
Figure 21.	Testing the analogue outputs.	44
Figure 22.	Testing the digital signals.	45
Figure 23.	Encoder input circuits.	46
Figure 24.	Isolated input and output circuits.	47
Figure 25.	SRV1+1 board layout	49

1. Introduction

This document is the Installation Manual for the MiniPTS 1+1, a member of the Quin Systems digital Programmable Transmission System (PTS) range.

The systems comprise hardware and software to control one or more servo motors, in conjunction with suitable high power drive systems for the motors. The hardware is highly modular, allowing systems to be easily expanded or upgraded. The software provides full control over all aspects of the system, but has a simple high-level user interface.

PLEASE READ THIS MANUAL BEFORE INSTALLATION.

It is very important that the guidelines for installation are observed, otherwise damage to the system or to the machine may occur. Quin Systems Limited accept no liability for damage or costs arising from incorrect or inadequate installation of the systems, or from incorrect programming of the system for the required application. Digital control systems are not simple, but can be used successfully to control industrial machinery and provide great improvements in reliability, performance and flexibility.

2. Unpacking and Inspection

Inspect the packaging for external signs of damage, if possible before signing the delivery receipt, as this may indicate that it has been mishandled in transit. When unpacking the system, keep all the packaging materials if possible. If it is necessary to ship the system to another site, or to return it for service, the original packing can be re-used.

Inspect the system carefully when it is unpacked. Check for any loose parts, any circuit boards loose in their card guides, cables not connected, or any bending of the case or chassis.

If any defect or damage is suspected, do not connect power to the system. Notify the carrier immediately, and contact your sales office or the Quin Systems Service Department:

Quin Systems Limited
Service Department
Oaklands Business Centre
Oaklands Park
Wokingham
Berkshire RG41 2FD
England

Telephone	+44 (0)118 977 1077
Fax	+44 (0)118 977 6728
Email	sales@quin.co.uk support@quin.co.uk
Web site	http://www.quin.co.uk/index.html

3. System Specifications

This section gives the overall specifications of the system, including mechanical details and environmental requirements.

3.1 Mechanical specification

The dimensions of the MiniPTS 1+1 system are as follows:

Height	209 mm (including mounting tabs)
Width	76 mm
Depth	60 mm
Weight	0.5 kg

Sufficient additional clearance must be left in front of the system for the serial port connectors on the front panel. The system is designed to be mounted in the normal orientation with the circuit boards vertical, to allow cooling air circulation by convection. There should be at least 50mm clearance above and below the unit to allow the air to circulate. If the unit cannot be mounted with the boards vertical, then a fan must be fitted to blow air through the unit.

3.2 Environmental specification

Temperature:	storage	0 to 100°C
	operating	0 to 45°C
Relative humidity:	20 to 80% non-condensing	

The system may be operated at higher ambient temperatures, but will require additional cooling such as forced air ventilation in order to do so. The system is normally supplied in a case or chassis with ventilation holes top and bottom, and therefore is not protected against dust, particles, or liquids. If necessary, the unit can be supplied in a suitable sealed cabinet. Please contact your sales office or Quin Systems directly for further details.

3.3 Power supply specification

The power supply requirement for the MiniPTS 1+1 is nominally 24V 0.1A d.c. The system accepts a supply voltage in the range 19–36V d.c. The power supply input is protected against reverse voltage connection.

Additional power supplies are required for the shaft encoders and the external digital input and output signals. Incremental shaft encoders normally require 5V d.c. The digital inputs and outputs use 24V d.c. for compatibility with PLC systems. The input and output lines are fitted with clamp diodes, which also provide some protection against reverse connection of the i/o supply. However, if the supply is reverse connected then large currents will flow through the protection diodes and they may be damaged unless an external fuse is fitted.

3.4 Relevant directives

The product is designed to be incorporated into a system for the control of machinery, and needs external equipment to enable it to fulfil this function. It must not be relied upon to provide safety-critical features such as guarding or emergency stop functions. It must not be put into service until the machinery into which it has been incorporated has been declared in conformity with the Machinery Directive 89/392/EEC and/or its relevant amendments.

The installation instructions in this manual should be followed in constructing a system which meets requirements.

The product has been tested in typical configurations and meets the EMC Directive 89/336/EEC, when fed from power supplies which meet 89/336/EEC and 92/31/EEC. The product uses only low voltages, and is therefore exempt under 73/23/EEC as amended by 93/68/EEC.

The product as normally supplied has low voltages accessible to touch, and must be mounted within a suitable cabinet to meet any required IP rating to BS EN 60529.

4. Mounting Details

The MiniPTS 1+1 system has mounting holes on the rear metal plate, for fixing to the electrical panel inside a cabinet. The unit is fixed with two M5 bolts through holes at the top and bottom of the unit. The fixing centres for these bolts are shown in the diagram below. Note that the bottom fixing hole is slotted and the top fixing hole is keyhole shaped to allow the unit to be slotted over the heads of the mounting bolts. Alternatively, the unit may be fitted with spring clips to allow it to be fitted to a standard 35mm symmetrical DIN rail.




Figure 1. Fixing centres for the MiniPTS 1+1.

5. Connections

The MiniPTS 1+1 systems have several connectors.

- 9 way D plug and socket P1 and S1 for the SERVOnet high speed network, based on CANbus.
- 9 way D socket S2 for the RS-232 programming terminal port.
- 9 way D socket S3 for the RS-485 port, used for Operator's Panel or low speed plc communications link such as Modbus or Data Highway.
- 9 way D sockets S4 and S5 for the two incremental encoder inputs.
- 10 way and 8 way two-part screw terminal connectors T1 and T2 for the isolated 24V digital inputs and outputs.
- 4 way two-part screw terminal connector T3 for the unit 24V and encoder 5V power supplies.
- 10 way two-part screw terminal connector T4 for the analogue input, analogue outputs, and the drive enable relay.

The front panel layout and connection details for the MiniPTS 1+1 are shown below.




Figure 2. MiniPTS 1+1 front panel layout

The RS-232 serial port on the MiniPTS 1+1 uses the 9 way D type socket S2. The pin connections to this are shown below.

S2 pin no.	Signal	S2 pin no.	Signal	
			RS-232	RS-485
1		6		
2	/TXD	7	RTS	TXD
3	/RXD	8	CTS	RXD
4		9		
5	GND			

Table 1: Serial port A connections

The RS-485 serial port for the Operator's Panel or Modbus interface uses the 9 way D type socket S3. The pin connections to this are shown below.

S3 pin no.	Signal		S3 pin no.	Signal
	RS-485	RS-232		
1	High termination		6	+Vbias
2	TXD	RTS	7	/TXD
3	RXD	CTS	8	/RXD
4	Low termination		9	
5	GND	GND		

Table 2: Serial port B connections

The SERVOnet high speed network ports use both a 9 way D type plug and a socket, P1 and S1. This allows units to be daisy chained together easily with standard cables, while allowing any unit to be bypassed by linking the two cables together. The pin connections to these are shown below. Note that this complies with the CAN in Automation (CiA) draft standard DS102 Version 2.0, CAN Physical Layer for Industrial Applications, but with additional signals used for error detection.

Pin no.	Signal	Pin no.	Signal
1	LINK1	6	CAN_0V
2	CAN_L	7	CAN_H
3	CAN_GND	8	CAN_ERR
4	LINK4	9	CAN_V+ (7–13V)
5	CAN_SHLD (screen)		

Table 3: SERVOnet (CANbus) connections

The encoders are connected via 9 way D type sockets S4 and S5. The pin connections to these are shown below.

S4, S5 pin no.	Signal	S4, S5 pin no.	Signal
1	A	6	/A
2	B	7	/B
3	Z	8	/Z
4	+5VE	9	0VE
5	SCREEN		

Table 4: Encoder connections : S4, S5

Two-part screw terminal blocks T1 and T2 are used for the 24V isolated digital input and output signals. The connections to T1 and T2 are as follows:

Screw terminal number	Signal
T1.1	Input 1
T1.2	Input 2
T1.3	Input 3
T1.4	Input 4
T1.5	Input 5
T1.6	Input 6
T1.7	Input 7
T1.8	Input 8
T1.9	0V I/O
T1.10	24V I/O
T2.1	Output 1
T2.2	Output 2
T2.3	Output 3
T2.4	Output 4
T2.5	Output 5
T2.6	Output 6
T2.7	Output 7
T2.8	Output 8

Table 5: Input/output connections : T1 and T2

Inputs 1 to 4 can be programmed for a fast response, and are used for referencing or position snapshot functions.

Terminal block T3 is used for the power supply connections for both the MiniPTS 1+1 itself and the incremental encoders. Note that the 24V power supply is not isolated from the internal supplies, and that the 0V connection at T3.1 should be earthed. The connections to T3 are as follows:

Screw terminal number	Signal
T3.1	0V supply
T3.2	+24V supply
T3.3	0V encoder supply
T3.4	+5V encoder supply

Table 6: Power supply connections : T3

Terminal block T4 is used for the analogue input, analogue output and enable relay connections. The connections to T4 are as follows:

Screw terminal number	Signal
T4.1	Screen (earth)
T4.2	Analogue input +
T4.3	Analogue input –
T4.4	Analogue input 0V
T4.5	Analogue output 2
T4.6	Analogue output 1
T4.7	Analogue output 0V
T4.8	Relay n.o.
T4.9	Relay common
T4.10	Relay n.c.

Table 7: Analogue signal connections : T4

All the screen connections are linked together to allow a single earth connection for all the cable screens. They are not connected to the system internal 0V supply. A clean separate earth connection is normally required to the 0V supply on terminal T3.1, or to one of the analogue 0V points on T4.4 or T4.7.

6. Electrical Installation

6.1 General

This section gives some guidelines for the electrical installation of the control system. The diagram below shows a typical installation, and will be used to highlight specific areas of interest in the following sections. Note that this is only a very simplified sketch, not a full installation wiring diagram. Details such as isolators, contactors and other switching arrangements are not shown but in most cases should be used. Please refer to the motor and drive manufacturer's instructions for further details on electrical installation.




Figure 3. General installation arrangement.

- Use separate trunking to keep all low voltage signal cables (encoder, resolver, command signal) away from three-phase, high current, or high voltage wiring.

6.2 Power supply

The MiniPTS 1+1 requires +24V d.c. provided by an external power supply. The mains input may be taken from the same three phase mains used for the motors and drives, but care must be taken to avoid introducing noise onto the supply to the control system.

For best results, follow the recommendations below.

- Use an isolation transformer and a line filter in the mains supply to the system. In some cases a line conditioner may be required.




Figure 4. Mains supply installation.

- Do **not** tie the input and output cables from the line conditioner together, or run them close together in a conduit or cable duct.
- Do **not** tie the three phase cables or the single phase supply cables together with any low voltage signal cables.

6.3 Earth connections

Earthing is very important in any electrical installation. It is an essential safety measure to prevent electric shock in case of any failure of the equipment, and is also used for screening between different units. It provides a ground reference point for all units in the system. Incorrect earth connection can result in erratic operation due to noise or earth loops, or may prevent the system from operating at all. These problems can be avoided by careful arrangement of the earth connections, and by such techniques as isolation.

- The earth connections from the isolation transformer and the line conditioner should be made in heavy gauge wire. All the earth connections should be connected together at one point, preferably on the electronics cabinet chassis.




Figure 5. Earth connections.

- Do **not** tie the earth wires together with any low voltage signal cables, or run them close together in the same conduit or cable duct.
- All screened cables should have their screens connected directly to earth, not via the system 0V power supply. This is very important, as otherwise noise and transients picked up in the screen will pass through the system, instead of being dissipated directly to earth.
- Note that the 24V power supply input is not isolated. An earth connection should be made to the 0V supply of the MiniPTS 1+1, either at the supply input connection on terminal T3.1, or at one of the analogue 0V connections on T4.4 or T4.7.

6.4 Connecting the motor to the drive

The motor should be connected to the drive according to the recommendations of the motor/drive manufacturer(s). A typical brushless d.c. motor is connected with two cables; one carries the power to the motor windings, and the other returns signals from the resolver to the drive for position sensing. The motor should be connected using cables as specified by the manufacturer. These cables usually have a strict specification with regard to size and length.




Figure 6. Motor connections.

- Do **not** tie the motor cable and resolver cable together, or run them together in a conduit or cable duct. The motor cable can carry high currents in normal operation, and the resolver cable carries low voltage signals back to the drive. The correct performance and accuracy of the motor and drive depend on the quality of the resolver signals.
- Use a screened cable with individually screened twisted pairs for the resolver signals from the motor to the drive. This prevents crosstalk and noise interfering with the resolver signals, and gives best performance.

6.5 Encoder signals

The position control system depends on the signals from the incremental encoder. These signals indicate both the distance travelled by the motor and the direction of travel. This information is used to calculate the required correction signal to send to the motor drive.

The cables used for the encoder signals should be high quality screened cables. When using the recommended encoders with complementary line driver outputs, the cable should use individually screened twisted pairs, with an overall cable screen as well. The cable screen should be connected directly to the main earth point, not via the control system 0V supply.




Figure 7. Encoder connection.

The encoder manufacturer's recommendations for cable type and maximum cable length must be observed. For the line driver output encoders the typical maximum cable length is about 70 m, but this does vary between different encoder manufacturers. It also depends on the cable type and termination used. If the machine installation requires a cable longer than the manufacturer's recommended maximum length, then it may be necessary to install an additional line driver unit to boost the encoder signals.

The MiniPTS 1+1 provides full isolation of the encoder input signals. This allows the encoders to be earthed without any danger of creating an earth loop, and prevents any noise picked up in the encoder cable from affecting the control system supply rails. It does require the use of an external power supply to provide the power for the encoders.

The diagram below shows the typical connections to the encoder, showing the pin numbers on the 9 way D sockets and the screw terminal numbers on terminal blocks T3 and T4.




Figure 8. Typical encoder connections.

With some brushless motors, the encoder signals may be derived from the resolver on the motor and provided as an output from the motor drive. In this case, the +5V connection between the encoder input 9 way D socket and the encoder output on the drive is not required. The encoder 0V must still be connected as shown.

6.6 Command signal and drive enable

The analogue command signal should be connected to the motor drive command input with a high quality screened twisted-pair cable. The command signal output from the PTS unit is connected to the positive input on the drive, and the 0V cmd signal is connected to the negative or common input on the drive. The cable screen should be connected directly to the main earth point, not to the control system 0V supply.

The motor off relay for each axis should be connected into the motor drive enable input, if available. This allows the controller to shut down the drive immediately when required by the MO motor off command, and on any error condition. The controller simply monitors the motor position when in the motor off state, and does not attempt to control the motor, holding the command signal output at 0V. If the motor off relay is not connected into the drive enable, then the motor and drive remain powered up in the motor off state, and any offset or drift in the drive causes the motor to drift slowly.




Figure 9. Command signal connection.

- The screened command signal cable should have its screen connected directly to earth, not via the system 0V power supply. This is very important, as otherwise noise and transients picked up in the screen will pass through the system, instead of being dissipated directly to earth.

The diagram below shows typical connections for the analogue output signals to the motor drive, showing the screw terminal numbers on terminal block T4. Note that only one of the possible different methods of connecting the drive enable signal are shown, with the drive using an optocoupled enable input.




Figure 10. Typical analogue output connections.

6.7 Digital inputs and outputs

The MiniPTS 1+1 provides eight digital inputs and eight digital outputs, all fully isolated. These may be used for several functions, such as monitoring pushbuttons or guards, controlling external solenoids or relays, or signalling to a programmable logic controller. The isolated interface allows +24V logic signals to be used.

This diagram shows typical input and output circuits, with any protection components and indicator LEDs shown as well.




Figure 11. Input and output circuits

7. Safety - Using Guards and Limits

All machines should include comprehensive safety features. This is essential both for normal safety considerations, and to comply with Health and Safety requirements. It can also prevent any unwanted interference with the machine while it is running.

All moving machinery must be guarded so that it cannot be reached by anybody while in motion. The guards should be fitted with guard switches or sensors, connected so as to immediately cut power from the motors when any guard is opened. On some machines, it may be useful to lock the guards closed by means of a solenoid to prevent them from being opened while the machine is running. This allows the machine to detect any attempt to open a guard and shut down the machine cleanly before unlocking the guard and allowing it to open.

Motors which have constraints or limits on their range of motion should be fitted with hard wired limit switches. These should cut power from the motors if any motor goes outside its limits of travel. The machine must also have one or more locking emergency stop pushbutton switches, accessible from several positions around the machine. Anyone operating or working on the machine must be able to instantly stop the machine at any time by hitting an emergency stop switch.

Guards, emergency stop and limit switches may be connected into the PTS motor control systems, by using the digital input lines. However, the programmable input functions on the PTS unit should only be used in addition to the conventional hard wired guard and limit switches, not to replace them. The digital inputs can be used to trigger a smooth shutdown sequence, or to generate a limit switch error and shut down immediately. The control system can then remove power from the motors and drives if required, under software control, by using a digital output line to switch the motor supply contactors. **In all installations the limit switches and guard switches MUST remove all electrical power from the motors and drives, independently of any action of the control system.** If power is removed from the control system, then again all power must be removed from the motors. This is easily done by connecting the onboard relay on each axis controller into the drive enable function, or into the control circuit for the motor and drive main contactors.

Note that in most cases, it is not necessary to remove power from the control system, only from all the high power equipment. If power to the control system and encoders can be maintained even when the motors and drives are shut down, then the system does not lose any position information. This can allow the machine to start up again much more quickly than if the control system is powered off as well, since the machine does not need to execute a complete initialization before it can be restarted.

For more information on programming the MiniPTS 1+1 for limit switch inputs and user defined functions, please refer to the descriptions of the DL and DI commands in the Input/Output Configuration section of the MiniPTS 1+1 Reference Manual.

8. Encoders

8.1 What is an encoder ?

An encoder used in a position or speed control system is simply a device to measure the position of some moving part of the machine. Often it is used to measure the shaft position of a motor, but it may equally well be used to read the position of, for example, a linear slide driven by a leadscrew mechanism. In all cases, the encoder measures position (or speed) and converts it to some electrical signal. In the discussions below, rotary encoders are described, but most of the information applies equally well to linear encoders.

8.2 Types of encoders

Encoders come in various types. All of them have the same basic design. They have a device to measure positions or angles, and one or more detectors which give signals when the measuring device is moved. In optical encoders, the measuring device is a glass or plastic disc with a graticule or diffraction grating pattern on it. Filament lamps or light emitting diodes (LEDs) shine light through the disc, passing through the pattern and into light sensitive detectors such as phototransistors. When the disc is moved, the motion of the grating causes the light falling on the photodetectors to vary. The resulting electrical signals from the photodetectors are amplified to produce a usable output signal, either TTL, open collector or line driver. Some of the basic encoder types are described below.

8.2.1 Single phase encoders

These have a single photodetector and a single track on the optical grating. They provide a pulse output which indicates the motion of the shaft and the distance travelled, but does not distinguish the direction of motion. They are used in speed controllers for some unidirectional motor systems. Very coarse single phase encoders are available, consisting of a disc with a number of slots cut into the rim, say ten or twenty slots, and a slotted optical switch or magnetic sensor. These can be used for coarse control or measurement of speed in some systems.




Figure 12. Single phase encoder signal.

8.2.2 Incremental or quadrature encoders

These have two photodetectors, but usually still only one track on the encoder disc. The two pulse signals are usually denoted by the names A and B. To use an incremental encoder to measure position, it is simply necessary to count the pulse cycles on the A and B tracks produced when the shaft is moved. By distinguishing the positive and negative directions, and counting either up or down appropriately, the count value represents the signed distance from the starting position to the current position.

In order to determine the direction of rotation of the shaft, the two detectors are aligned such that the signals from the one track on the disc appear phase shifted on one detector relative to the other by nominally 90° , a quarter of a cycle. When two signals have this 90° phase relationship, they are described as being in quadrature. This phase shift between the two signals allows the direction of motion to be distinguished, as well as the distance travelled. In one direction the track A signal will lead the track B signal, while in the opposite direction they are reversed, and the track B signal will lead the track A signal. This allows incremental encoders to be used for position feedback in servo motor control systems. In addition, it is possible to detect every transition on each signal track, to increase the available resolution of the encoder by a factor of four.




Figure 13. Incremental encoder signals and multiplication.

The major drawback of incremental encoders is that when a system is first turned on, there is no information about the current motor position. The encoder indicates only how far and in what direction the motor moves from this starting position. To provide a datum point, many incremental encoders have an extra track on their optical disc and a third photodetector. This third track, known as the marker or reference track, gives only one pulse per complete revolution of the encoder shaft. It is used to define an absolute zero position for the shaft, by moving until the marker signal is detected and setting the position counters to zero at that point. The marker signal is typically only one half or one quarter of an encoder cycle, and so provides an accurate datum position.




Figure 14. Incremental encoder marker signals.

Incremental encoders are readily available from 100 to 2500 counts per turn, and hardware multiplication of the encoder signals increases this by four times to 10,000 counts per turn. There are also now available incremental encoders using semiconductor lasers and interferometric techniques that give 81,000 counts per turn as standard, and up to 16 times this with hardware interpolation (1,296,000 counts per turn).

8.2.3 Absolute encoders

Absolute encoders have several tracks on the optical disc, and several photodetectors. The transitions between dark and light portions of the tracks on the encoder disc are arranged such that the parallel data available from the photodetectors represents the absolute position of the shaft. Absolute encoders are available from 8 bits to 14 bits wide, or even more, and with either binary, BCD or Gray code outputs. Gray code is often used to avoid possible problems when sampling the data while it is changing. With Gray code, only one bit of the data changes at any one encoder line transition, so that even if the data output changes while it is sampled, the error can only be ± 1 bit.

Absolute encoders overcome the problem with incremental encoders of finding the zero position when the system is first started, since the absolute position value is always available. However, they are much more expensive than incremental encoders, they have to be physically larger to get the increased number of tracks onto the disc, and they require as many wires in the connecting cable as they have data bits. They also have the limitation that the position values are defined for only one revolution of the shaft, and then they cycle through the same values again. In contrast, incremental encoders with their counters may be used over any range of position values, limited only by the size of the counters used. In addition, absolute encoders of greater than 12 bits resolution (4096 counts per turn) are less commonly available and very expensive.

8.2.4 Hybrid encoders

Hybrid encoders are a combination of incremental and absolute encoders, in an attempt to work around the drawbacks of the two types. They have both incremental and absolute data signals, but usually only at low to medium resolution. They use a low resolution absolute encoder disc of, say, 8 bits precision, in conjunction with a higher resolution incremental encoder track. This gives some absolute position information at all times, and the incremental track allows finer position control than just the absolute data.

8.2.5 CANopen encoders

The MiniPTS 1+1 has provision for using CANopen compatible absolute encoders. These are single or multiturn absolute encoders with a CANbus interface, having a software protocol that conforms to the CANopen encoder profile. They have typically 12 bits of position data per turn (4096 counts), and often have up to 12 bits of turns count data (4096 turns) available as well. The data from the encoder is returned in a CANopen message, when requested by the axis card or in response to a regular clock tick message. This avoids the cabling problems of parallel absolute encoders, while giving absolute position information at all times.

8.3 Choosing an encoder

The MiniPTS 1+1 is designed to use incremental encoders with complementary line driver outputs. These are used for increased signal integrity and noise rejection as compared with cheaper encoders having only single ended output signals. The main criterion for selecting a particular encoder are the number of counts or resolution of the encoder, its mechanical specification for vibration, sealing etc., and its physical size.

The mechanical and size requirements for the encoder are dictated by the machine design, and do not affect the control system. The choice of encoder resolution does affect the setup of the control system, but the MiniPTS 1+1 is more flexible than most in its facilities for accommodating different encoders.

8.3.1 Maximum count rate

The maximum encoder cycle rate for the MiniPTS 1+1 is 300 kHz, giving an absolute maximum count rate of 1.2 MHz after the hardware $\times 4$ multiplication. This sets a maximum limit on the shaft speed for a given resolution encoder, or alternatively sets a maximum encoder resolution at a given shaft speed. For example, a 2,500 line encoder (giving 10,000 counts) reaches the count rate limit at

$$\omega = 1200000 \div 10000 \times 60 = 7200(\text{r.p.m.})$$

Conversely, for a system with a maximum shaft speed of 6,000 r.p.m., the maximum encoder resolution that can be used is

$$R = (1200000 \div 6000) \times 60 = 12000(\text{counts})$$

Note that when using the normal move facilities on the MiniPTS 1+1, the set speed value is limited to a maximum of 1,000,000 counts per second, giving some headroom for speed variations around the nominal speed.

8.3.2 Machine cycle length

It is often convenient to choose an encoder such the machine cycle length is either a nice round number of encoder counts or at least a whole number of encoder counts, although this is not necessary with the MiniPTS 1+1. It makes setting up the system simpler because the parameter values are more easily related both to the machine geometry and its operation. The MiniPTS 1+1 can be programmed for any encoder cycle length, using the SB set bounds command.

If it is not possible to choose an encoder such that there is a whole number of encoder counts per machine cycle, then the system must use some technique for handling the fractional counts at end of each cycle. Otherwise, the odd part of a count will be lost on every machine cycle, and the motor position will drift relative to the rest of the machine. Using the auto-referencing facilities of the MiniPTS 1+1, it is possible to allow for this by checking the measured motor position every cycle against the zero marker signal. It is even possible to set up the system to check on only one of several possible marker positions, once the system is correctly initialised.

For more information on using the bounds and auto-referencing commands please refer to the PTS Reference Manual.

8.4 Encoder installation

Optical encoders with their glass or plastic disc are precision devices, and are relatively fragile. It is important that the encoder is mounted correctly so as to avoid any damage or excessive wear that could reduce its working life. The following points should be considered when installing an encoder.

- The encoder shaft should not be subject to any end or side thrust, and there should be no misalignment of the shaft. All of these will cause excessive wear of the encoder bearings, and will give rise to additional friction in the system. The encoder shaft should be connected by means of a suitable flexible coupling. These are available specifically for use with shaft encoders, designed for minimum backlash. The data sheet for any particular encoder includes the maximum permissible limits for the shaft loading.
- If possible, do not mount the encoder in an exposed protruding position, where it may be easily damaged.
- When using an encoder with a standard housing, avoid contact with oil or water as this may damage the internal electronics. Where the application requires a higher degree of environmental protection for the encoder, use one with an IP sealing rating or heavy duty housing.
- If the encoder is driven by a pulley which itself is chain or belt driven, the pulley should be mounted in its own bearings, and a coupling used to connect the encoder to the pulley. This is to avoid excessive side loads on the encoder shaft due to the sideways forces acting on the pulley.
- Do not pull the encoder cable. Make sure that the cable can not be caught up in any moving parts of the machine.
- Keep the encoder cable length as short as possible. If the cable is too long, it will be more susceptible to electrical noise. It is also necessary to ensure that the encoder supply voltage is still correct at the encoder end of the cable, as a long cable can produce a significant drop in the supply voltage. Check the resistance of the cable, and the supply current requirements of the encoder. If necessary, adjust the local power supply to compensate for the losses, but be careful not to exceed the supply voltage rating of the encoder or it will be damaged. Alternatively, either use several wires in the cable for the supply connections, or use a remote sense connection so that the power supply can regulate for the correct voltage at the far end of the cable.

9. Motors

9.1 Types of motor

There are many different types of electric motor, including d.c. servo motors, a.c. motors, and brushless servo motors. Each type has quite different performance characteristics, and is suitable for different applications.

Normal brushed d.c. servo motors are widely used. They develop full torque over a wide speed range, and are easily controlled. However, the torque does fall off at speeds near the maximum speed limit for the motor, and they have only a limited intermittent overdrive capability. The maximum torque available at a given speed is limited by the commutation of the motor brushes. The brushes are also subject to wear, and must be inspected and replaced at regular intervals. The diagram below shows a typical torque-speed plot for a d.c. servo motor.




Figure 15. Torque-speed curve for a d.c. motor.

In contrast, a.c. motors are normally used with inverter drives in applications where the motor speed is constant or nearly so. They are designed for continuous near-synchronous operation, but they can be controlled with variable frequency inverter drives. They have poor low speed torque, and do not particularly have any intermittent high torque capability. However, since they do not require brushes, they have lower maintenance requirements than brushed d.c. motors. The diagram below shows a typical torque-speed curve for an a.c. motor.




Figure 16. Torque-speed curve for an a.c. motor.

Brushless motors combine the best features of both d.c. and a.c. motors. They have high torque at all speeds, in some cases right up to the maximum speed of the motor. They have no brushes, giving improved reliability and lower maintenance than a brushed d.c. motor, and they do not suffer from the commutation limiting effects at high speeds and torques. They have a very high intermittent overdrive capability, up to as much as ten times the continuous rating for short periods. This is very useful in applications such as indexing, where the motor starts and stops very rapidly, but is not running continuously. They dissipate excess heat very quickly, because the motor windings are in the static outer case of the motor, not on the armature. This means they can run continuously at high power levels without overheating internally. All these factors combine to make brushless motors ideally suited for use in servo control systems. The diagram below shows a typical torque-speed curve for a brushless motor.




Figure 17. Torque-speed curve for a brushless motor.

9.2 Choosing a motor

The choice of motor for a particular application depends on several factors. Some of these are given below.

- Maximum torque required.
- Continuous torque required (r.m.s.).
- Maximum motor shaft speed.
- Maximum acceleration rate.

The torque is the turning effort required from the motor in order to accelerate the mechanical load or system at the desired rate. It is usually measured in Newton metres (Nm), gramme centimetres (gcm), pound feet (lb ft) or ounce inches (oz in). In order to calculate the torque required from the motor, it is necessary to find out the following information about the mechanical system.

- The reflected total inertia of the system or load, at the motor shaft.
- The reflected total friction of the load.
- The internal motor inertia and friction.
- The maximum acceleration rate of the motor.
- Any gear or pulley ratios in the mechanical system.

For example, consider a motor driving a load via a belt and pulleys. The total torque required from the motor is given by :

$$T = \left(\left(\frac{D_1}{D_2} \right)^2 I_L + I_M \right) \frac{d^2 \theta}{dt^2} + \frac{D_1}{D_2} F_L + F_M$$

where

- T = total motor torque required
- D_1 = diameter of motor pulley
- D_2 = diameter of load pulley
- I_L = inertia of load
- I_M = inertia of motor
- $\frac{d^2 \theta}{dt^2}$ = acceleration at motor shaft
- F_L = friction torque of load
- F_M = friction of motor.

In most cases, the inertia and friction can be assumed constant, unless the system has a changing load. In this case the maximum possible load should be used in the calculations. The required velocity profile of the motor should be sketched out by plotting motor velocity against time. The slope of this gives the motor acceleration, and thus the maximum required acceleration can be found from the steepest slope on the graph. This acceleration value can then be substituted in the torque equation for a given motor to see if the motor is powerful enough to do the job.

This can be repeated along the velocity-time plot for all accelerations to give a graph of torque against time. This can be used to find the average or r.m.s. continuous torque required by the system. Servo motors are often specified with both a continuous and a peak torque rating, and they should be chosen such that the torque requirement of the machine is well within the capacity of the motor. Care must also be taken to ensure that the maximum speed of the motor is not exceeded.

Note that if too large a motor is selected, the motor inertia is higher than for a smaller motor. This affects the maximum acceleration that the motor produces. It is not always the largest or most powerful motor that accelerates the load at the quickest rate. Also note that maximum power transfer from the motor into the load is obtained if the motor inertia and load inertia are similar.

The ideal motor should have as high a torque to inertia ratio as possible. Pancake or printed armature motors are often used because they have low rotor inertias. This is also another advantage of brushless motors, in that they have low rotor inertias. This is because the rotor often does not have any electrical windings but consists simply of a permanent magnet on a shaft.

9.3 Mounting the motor

The motor must be mounted rigidly to the structure of the machine or to a solid floor. If it is not mounted securely, it may vibrate or oscillate when the motor is powered up and the position or velocity control loops closed. The motor exerts as much torque on its mountings as it does on the load. If the mountings are flexible, they may form a resonant system, with the motor supplying plenty of power to sustain severe oscillations.

9.4 Connecting the motor to the load

The motor shaft must be connected securely to the load. This may be by means of a drive shaft, a toothed belt and pulleys, or by a gearbox. In all cases the coupling between the motor and the load must be as stiff as possible, and must have minimum backlash. At the same time, care must be taken to avoid adding any unnecessary friction into the system, as this reduces the performance of the servo system.

A common problem when connecting the motor to its load is backlash. This is usually found in gearboxes, where the input gear is allowed to move by a small amount between the teeth of the output gear, while the output gear is stationary. A similar effect is seen if the motor mountings are loose or sloppy, or if the coupling between motor and load is too flexible. The effect of backlash is not just a loss of position accuracy, but may in extreme cases result in a highly unstable system. All possible precautions must be taken to minimise or eliminate backlash in the system.

10. Tuning the Position Control Loop

10.1 General

Tuning the position loop is the process of adjusting the various gain terms in the controller to get the best response from the motor and drive. The dynamic behaviour of the system depends on these gain constants, and on the mechanical characteristics of the system being controlled. The easiest way to choose suitable gain constants is by experiment, using the real motor and load. It is possible to calculate the required parameters, but this requires detailed knowledge of the motor and load transfer functions, which are not always available and are difficult to measure. In practice, with a software controlled system such as the MiniPTS 1+1 it is very simple and much quicker just to experiment with gain settings. The MiniPTS 1+1 allows the gain values for any motor to be changed at any time, even while the motor is moving, just by sending simple commands to the system via a standard computer terminal. In addition, there are several diagnostic aids on the system to provide information about the performance of the system.

10.2 Control algorithm

The motor control system operates by sampling the position of the motor at regular intervals, and calculating a motor demand signal according to some control algorithm. The algorithm used is of the following form.

$$V_{out} = KP e_i + KI \sum e_i + KD(e_i - e_{i-1}) - KV(p_i - p_{i-1}) + KF(d_i - d_{i-1})$$

where

- KP = proportional gain constant
- KI = integral gain constant
- KD = differential gain constant
- KV = velocity feedback gain constant
- KF = velocity feed-forward gain constant
- e_i = position error (= demand position – measured position)
- d_i = demand position
- p_i = measured position

The actual scaling between position error and output voltage, for proportional gain only, is as follows:

$$V_{out} = \text{Error} \times \frac{KP}{256} \times \frac{10}{2048} \text{Volts}$$

where KP is the proportional gain term, and Error is the position error, measured in encoder counts. The other control terms have similar scalings.

10.3 Monitoring the performance

There are two main facilities provided in the MiniPTS 1+1 to help to monitor the performance of the motors.

- Continuous display mode.
The continuous display mode, accessed by the DM command, prints via the serial port a continuous display of the demand position, measured position, and position error on the current channel.
- Monitor function.
Any unused analogue output may be programmed for use as a monitor output signal. The monitor output can be programmed to output a signal proportional to one of a wide range of measured values. This signal may be viewed on an oscilloscope or a chart recorder. This is particularly useful for seeing the effects of changes in the gain terms when used in conjunction with a storage oscilloscope, as the results can be seen immediately on the display trace.
- PTS Toolkit tuning display.
The PTS Toolkit PC based front end software includes a simple tuning display. It allows the demand and measured speeds of any one axis to be plotted on the screen, together with the position error. It uses the serial port to upload the information from the PTS unit. It can operate in continuous mode with some limitations in sample rate, or in historical mode, where data is stored and buffered at the full system sample rate and every sample is uploaded to the PC.

These facilities are described fully in the MiniPTS 1+1 Reference Manual.

10.4 A simple tuning procedure

Tuning a control system is never easy, especially if it is necessary to wring the last ounce of performance out of a motor. However, in most cases this simple outline procedure is a useful starting point for a fuller tuning exercise on a system.

NOTE : This procedure involves trying to set the system into oscillation in order to find an upper limit on the gain parameters. If this is likely to cause any problems or damage to the system, or it is impractical for any reason, then this procedure should not be followed.

- Firstly, the motor and drive must themselves be correctly set up. On most drive systems, the drive unit operates a velocity control loop to control the speed of the motor according to the speed demand signal it receives. This inner control loop should be set up according to the drive and motor manufacturer's instructions. This should be done with the servo controller either disconnected or in the motor off state, so that it is not trying to control the position at the same time.
- Check that the control system is correctly connected to the drive and to the position encoder.

- Either :
 Connect an oscilloscope or chart recorder to the analogue monitor output, select the desired monitor function with the SF command, and set the monitor gain to some non-zero value with the KM command, say 400. For example, setting SF to 2 selects the measured velocity as the monitor function, so that the output voltage represents the measured change in motor position at each sample. Set up the auxiliary output channel number with the AO command.
 Or :
 Use the PTS Toolkit tuning display on a PC connected to the serial port to display the motor demand speed, measured speed and position error.
- Set the proportional gain to some low value, say 50, and set all other gain terms to zero. The default settings for the gain parameters are 256 for KP and KF, and zero for all other gain values. Set the velocity and acceleration with the SV and SA commands to some suitable low values, depending on the resolution of the encoder.
- Enable the position control action with the PC command. If the motor immediately runs at high speed in one direction and then stops, giving a “motor position error” error message, then the sense of the encoder is reversed. Correct this by swapping one pair of encoder wires, or by setting the appropriate flag bit in the control word for the channel using the CW command. The following stages assume that the system is now correctly controlling the motor position.
- Try executing some simple move commands, such as MR1000. The motor should move as instructed. If at any time it starts to run at high speed in one direction and stops, as described above, then check the encoder connections again. If it moves as requested but starts to vibrate or oscillate, then the gain is already too high. Reduce it by halves until the vibration stops. The monitor output should show something approximating a trapezoidal or triangular velocity profile for the move.




Figure 18. Motor performance for detuned system.

- When the motor is following some simple slow move commands correctly, the next stage is to try some fast moves. This is like giving the system a step function. Increase the speed and acceleration to larger values, and try some move commands again. Repeat this until the motor is making a very sudden motion.
- Set the system to repeatedly execute this sudden move, with a pause between each move to allow the system to settle. An example command string is :

MR1000/WT128/MR-1000/WT128/RP

This command string sets up a loop where the motor moves 1000 counts positive, pauses for half a second, moves back 1000 counts negative to its start position, and waits another half second. This repeats until stopped by using the AX abort execution or ER end repeat commands.




Figure 19. Motor performance for faster moves.

- While the system is executing this move command loop, slowly increase the proportional gain with the KP command until overshoot or ringing occurs at the end of each move. This is an indication that the system is beginning to become unstable. It should be possible to increase the gain to the point where the oscillation is sustained indefinitely, or decays away slowly. This is the highest usable value of KP without making the system completely unstable, although it is of no practical use because of the oscillations.




Figure 20. Motor performance with oscillation.

- Now increase the velocity feedback gain with the KV command. Velocity feedback adds damping into the system, and should begin to reduce the amplitude of the oscillations. This should be visible on the monitor signal. Continue to increase the value of KV until the oscillations stop, and there is little or no ringing at the end of each move. The KV term usually can be increased to a much larger value than the KP term. On many systems, it is possible to increase KV to the point where no oscillations or ringing occurs, and the time taken to reach the target position is a minimum. This is called critical damping.

NOTE : On some very low inertia motors with small loads, the KV term may prove ineffective in damping the oscillations, and may make them worse. In this case, an additional external source of damping such as a tachogenerator must be fitted to the motor. This provides instant velocity feedback to the motor drive and is not subject to the sample time constraints of a digital system. Tachogenerators may of course be used with any systems, not just low inertia systems.

- Stop the move command loop with the AX or ER command. If it is possible to run the machine at constant speed in one direction, then the KF feed-forward gain may be set up at this point as well. If not, it will have to be set up during more normal operation of the system. Set the speed to the desired operating speed of the motor. Turn on the continuous position display with the DM command, and start the motor at constant velocity with the VC command. The third column in the DM display shows the position error. Increase the value of KF and note that the position error values should decrease. KF may be increased until the position is approximately zero, at which point the feed-forward gain is compensating for the velocity lag present in the system with proportional gain only. The KF value may be increased further to the point where the motor position is ahead of the demand position, if required, without any problems.

This procedure, although it only describes setting up some of the gain terms, is sufficient in many cases to give acceptable performance from the motor system. However, an acceptable setup for any particular operation may not be ideal for a different operation, so it is useful to experiment with many different moves and profiles to find the best compromise. Clearly, the most important operation for the purpose of tuning the motors is the normal operation cycle of the machine. Note that by using the command sequence facilities on the system, it is quite feasible to change gain settings automatically, in response to an input signal or according to a set programme. This would be used, for example, on a robot arm, where the ideal setup depends on the load carried by the arm.

Tuning any control system is not a simple process, particularly a servo control system with a very fast response time. Most literature on control systems and tuning describes the application of controllers to large process plant, where the plant response time to a change is very long compared to the sample time of the controller. The situation is often quite different when dealing with high speed electric motors, which now can have mechanical time constants down to about 10 ms with no external load.

11. Testing the System

11.1 General

This section describes some simple test procedures for some parts of the PTS systems. These do not comprise a full system test, but may be useful to verify the basic operation of the system, the motor and the encoder.

All these tests require the use of a computer terminal or VDU with an RS-232 serial port. A simple portable terminal is sufficient for most tests. Some tests require additional test equipment, as given below.

11.2 Serial port

The system prints characters via the RS-232 serial port when it is powered up. These may be detected by using the terminal, or with a serial data analyser. The system normally prints a version and copyright message, followed by the '>' or ':' prompt character. An example for a MiniPTS 1+1 is shown here.

```
MiniPTS 1+1 Version 1.9.1.1
Copyright 1998 Quin Systems Ltd

Motor1 found
Motor2 found

1:
Restoring parameters | Done
1:
```

If there is no response from the unit, or the messages are garbled, then check the connections between the terminal and the system, and also check that the serial data format on the terminal is set to eight data bits, one stop bit, no parity and 9600 baud. If there is still no response from the system on power-up, the serial data signals should be checked with a data analyser or an oscilloscope, to verify whether the system is actually sending any characters out.

Once the startup message is received, try sending characters to the system by typing them on the terminal keyboard. Each character should be echoed (printed on the terminal screen) as it is typed on the keyboard. Press the Return or Enter key. This sends the characters to the system as a command string. The system should respond, probably with an error message, followed by the command prompt character as before.

Once communications with the system are established via the serial port, it is possible to use the normal command set to test most other features of the system.

11.3 Encoder

Ensure that the shaft encoder is connected to the inputs of the MiniPTS 1+1, and that the motor power is switched off. Type “DM” on the keyboard, and press Return. The system should start displaying data continuously, giving the demand position, measured position, and position error information.

The measured position data in the second column of data gives the current position, in encoder counts, of the encoder shaft. Turn the shaft by hand, and the displayed position data should change, showing that the system has measured the change in position of the shaft. Note that the three red LEDs should be switching on and off rapidly as the encoder is turned. The LED’s light for the “off” polarity of each encoder signal.

If the encoder position counts up and down by only one count, then one of the two phases of the encoder signals is not being detected. If the encoder position value does not change at all, then either both phase signals are missing, the encoder power supply is missing or off, or the light source in the encoder is faulty. If the position tends to count either up or down whichever direction the shaft is turned, then the track A and B signals are mixed up with their complementary signals, such that instead of the system receiving two signals in quadrature, it always receives two signals in opposite phase regardless of the shaft direction. These problems can be confirmed by monitoring the encoder signals with an oscilloscope, or by observing the indicator LEDs.

If the encoder marker signal is used as the position reference signal, then this should also be checked. Type “DZ1/RM1” to enable referencing on the encoder marker pulse. Then type “WF/DF/RP”. The system should respond with the ‘W’ prompt to indicate that it is waiting for the reference signal. Turn the encoder shaft so that it passes through the marker position, and the system should display the value of the reference position error, measured on the desired transition of the reference input signal. Continue to turn the encoder shaft to verify the operation of the reference input and marker signal as required. If the system does not display the value of the reference error, but stays in the waiting state with the ‘W’ prompt, then check that the marker input signal is present with an oscilloscope. If the encoder marker signal is not detected, there may be some problem with the encoder or the connections to it. Type “AX/WE” followed by Return when finished, to stop the wait command loop.

11.4 Motor enable relay

Equipment required :

Multimeter or DVM with resistance or continuity measurement facilities.

Set the multimeter to its resistance or continuity test range. To check the function of the motor enable relay, the meter should be connected between the *relay common* signal and either the *relay n.o.* or *relay n.c.* signals as required.

Type “MO<Return>” to set the system into the motor off state. Check that the relay normally open contacts are open circuit, and that the normally closed contacts are short circuit. Type “PC<Return>” to go to the position control state. Check that the normally open contacts are now closed, and the normally closed contacts are open.

11.5 Command signal

Equipment required :

Multimeter or DVM, or an oscilloscope.

Make sure that power is still not connected to the motors and drives. Set the multimeter to the 10V range. Connect the meter between the *command signal* output and *0V cmd*.

Press Return to get the current prompt character. If the prompt is neither of the normal idle state prompt characters '>' or ':', then type "ST<Return>" to return to idle. If the idle prompt is the ':' motor off prompt, type "PC<Return>" to put the system into position control mode. Type "ZC<Return>" to ensure that the current encoder position is defined as zero. Set the maximum following error and timeout parameters to large values by typing "SE10000/TO2000<Return>" to stop the error checks from interrupting the tests.

Check that the voltage on the command signal output is close to 0V. Type in a simple move command, such as "MA1000<Return>". Check that the command signal voltage increases gradually towards +10V. Type "MA-1000<Return>" and check that the command signal voltage decreases gradually towards -10V. Type "MA0<Return>" and check that the command signal returns to 0V.




Figure 21. Testing the analogue outputs.

11.6 Digital signals

Equipment required :

- Multimeter or DVM.
- Connecting wire or pushbutton switch.
- External power supply.

The digital signals may be checked using the multimeter in conjunction with the manual input and output commands. Set the external power supply to the voltage required by the digital inputs, usually +24V. Begin with all input and output lines disconnected from the external system. Type “RI<Return>” and check that all inputs are shown with a ‘0’. Connect the external power supply to each input line in turn, and use the RI command to verify the operation of each line.

Connect the external power supply to the +24V and 0V I/O connections. Connect the multimeter in turn to each output line, and using the SO set output and CO clear output commands, check the operation of the line. The SO command turns on the output optical isolator, pulling the output signal up to +24V, and the CO command turns the output isolator off.




Figure 22. Testing the digital signals.

12. Electrical Details

12.1 Signal names

The signal names in this document follow certain conventions for simplicity.

A '/' prefix is used on the encoder signals to denote a complementary or inverted signal. Thus the /A signal is the complement of the A signal.

A '+' or '-' suffix is used to denote the high or low side of the plant connections. Connections with a '+' suffix are the high side of a signal, and those with a '-' suffix are the low side. For example, the analogue input+ and analogue input- connections are the high and low plant connections respectively for the analogue input signal.

NOTE: It is important that the polarity of the plant connections is correct. If these are reversed, the optical isolator devices on the MiniPTS 1+1 may be damaged.

12.2 Encoder input circuits

The encoder input circuit is shown in the diagram below. Note that the three red LEDs for each encoder light for the "off" polarity of the encoder signals.




Figure 23. Encoder input circuits.

12.3 Isolated input and output circuits

Circuit diagrams for the isolated digital inputs and outputs are shown in the diagram below.

The MiniPTS 1+1 includes extra protection components, as shown. The reversed diode on the input lines and the diodes on the output lines provide reverse voltage protection. An indicator LED is also fitted on inputs and outputs to show the state of the line.




Figure 24. Isolated input and output circuits.

If the outputs are overloaded by switching too high a current, the output optocoupler devices may be damaged. Care should be taken to avoid shorting the switched outputs to the 24V i/o supply rails.

12.4 Electrical characteristics

External power supplies :

Encoder supply	+5V
Digital i/o supply	+24V

Encoder inputs :

Input signal levels	+5V nominal
Isolation voltage	250V a.c. peak or d.c.
Frequency (count rate)	300 kHz maximum (1.2×10^6 counts per second)
Track A input leads track B input for positive direction	

Analogue input :

Input range	$\pm 10V$ (differential)
Resolution	12 bits

Analogue outputs :

Output range	$\pm 10V$
Resolution	12 bits
Output impedance	100 Ω

Digital inputs :

Voltage rating	+24V nominal
Input current	typical: 10–20 mA
	maximum: 50 mA
Threshold voltage	10–16V
Reverse voltage	+5V maximum
Isolation voltage	250V a.c. peak or d.c.

Digital outputs :

Saturation voltage (output on)	1.9V maximum (at full load current)
Load current	100 mA maximum
Reverse voltage	+5V maximum
Isolation voltage	250V a.c. peak or d.c.

Relay contacts :

Rated load	0.5A 60V a.c. peak or d.c.
Switch power maximum	30W 30VA
Contact resistance	50 m Ω maximum
Operate/release time	5 ms maximum
Service life	10^7 operations (24V 0.2A d.c. resistive load)

13. Board Configuration

This section gives details of the configuration options on the SRV1+1 board used in the MiniPTS 1+1. It is described here for completeness, although the settings are not normally changed. The board is set up as described below when shipped.

The SRV1+1 board is used in the MiniPTS 1+1 system.

The jumper links on the SRV1+1 are described here.





Figure 25. SRV1+1 board layout

J1: Reset and interrupt configuration

Jumper J1 is used to set up the power up reset options and interrupt signals for the MC68376 processor. It is normally factory set when supplied to suit the particular firmware fitted, but is described here for completeness.



The normal configuration is with /DUARTIRQ linked to /IRQ2 (pins 5–6).

J1 is located at the top right of the module, with pin 1 at the top left.

J2: Serial port A override

The serial ports on the SRV1+1 module are configured by the software for RS-232 or RS-485 as required, to reduce the number of jumpers that need to be configured by the customer for different applications. Jumper J2 allows the software configuration for port A to be overridden for testing. For normal operation under software control, link J2 pins 1 and 2. To force RS-232 operation, link pins 3 and 4.

Index

– suffix	46	Operator's Panel	11
+ suffix	46	power supplies	13
/ prefix	46	serial port	11
		SERVOnet	11
A		connectors	10
a.c. motors	31	continuous display mode	37
absolute encoders	27	control algorithm	36
acceleration	34	cooling	7
address for service or repair	6	couplings	35
adjusting KF	41	critical damping	40
adjusting KP	40	CW command	38
adjusting KV	40	D	
analogue connections	13	d.c. servo motors	30
analogue input	48	datum position	26
analogue output	37	depth	7
analogue outputs	48	digital inputs and outputs	22, 48
auto-referencing	28	dimensions	7
average torque	34	drive	
B		connections	17
backlash	35	enable connections	13
baud rate	42	enable relay	43
board layout	49	E	
brushed motors	30	earth connections	16
brushless motors	32	electrical characteristics	48
C		electronic mail	6
cable layout	15	e-mail address	6
CANbus connections	11	emergency stop	23
CANopen encoders	27	enable relay	43
choice of motor	33	connections	21
command signal		enable relay connections	13
connections	13	encoder	
scaling	36	absolute	27
testing	44	cables	18
command signal connections	21	CANopen	27
complementary signals	28	connections	12, 19
connections		count rate	28
analogue inputs and outputs	13	counts	26
CANbus	11	faults	43
command signal	13, 21	hybrid	27
drive enable	13	incremental	25
earth	16	input circuit	46
enable relay	13, 21	input signals	48
encoder	12, 19	installation	29
inputs and outputs	12	mounting	29
motor and drive	17	multiplication	25
		power supply	19
		reversal	38
		testing	43

types of encoder	24	low inertia motors	40
environmental specification	7		
external power supplies	48	M	
external power supply for encoder	19	machine cycle length	28
F		machine guards	23
fax number	6	maintaining position information	23
fixing centres	9	marker signal	26
friction	34	marker signal test	43
G		maximum count rate	28
gain adjustment	40	measured position display	43
gray code	27	mechanical specification	7
guards	23	monitor function	37
H		monitor signal test	44
height	7	monitoring performance	37
home position	26	motor	
humidity	7	connections	17
hybrid encoders	27	enable relay	43
I		inertia	34
incremental encoders	25	installation	35
inertia	34	selection	33
initial position	26	types of motor	30
input and output circuits	22, 47	mounting details	9
input line testing	45	mounting the encoder	29
input lines	22	mounting the motor	35
input/output connections	12	N	
interrupt configuration : J1	49	non-integer encoder counts	28
isolated inputs and outputs	22, 48	O	
isolation transformer	15	Operator's Panel connections	11
J		output line testing	45
J1 : interrupt configuration	49	output lines	22
J2 : serial port A override	50	output scaling	36
jumper locations	49	P	
K		performance monitoring	37
KF adjustment	41	position display mode	37
KP adjustment	40	position encoders	24
KV adjustment	40	power down	23
L		power supplies	48
limit switches	23	connections	13
line drivers	28	encoder	19
		external	48
		proportional gain	40
		Q	
		quadrature	25

R

r.m.s. torque	34
reference position	26
reference signal	26
relay	43
relay contacts	48
reversed encoder	38

S

serial data format	42
serial port	
connections	11
testing	42
serial port A override : J2	50
service department address	6
SERVOnet connections	11
set bounds command	28
setting KF	41
setting KP	40
setting KV	40
shaft encoders	24
shutdown	23
signal names	46
signal polarity	46
system tests	42

T

tachogenerator	40
telephone number	6
temperature range	7
testing	
command and monitor signals	44
command signal	44
digital inputs and outputs	45
enable relay	43
encoder	43
marker signal	43
serial port	42
torque calculation	33
torque-speed curves	30–32
tuning	36
tuning procedure	37
types of motor	30

V

velocity feedback	40
velocity feed-forward	41
velocity profile	34

W

weight	7
width	7
wiring faults	43

Z

zero position	26
---------------	----